29 Duncan Road Morrisville, Vermont 05661 Phone 802-888-1936 info@crothersenvironmental.com

December 18, 2013

Alexander Aman, Asbestos NESHAP Coordinator
U.S. Environmental Protection Agency – Region 1
5 Post Office Square – Suite 100
Boston, MA 02109-3912

RE: Waterbury State Office Complex (WSOC) – Building 1/2/3 South Asbestos NESHAP Notifications

Dear Mr. Aman,

In accordance with your request during your December 4, 2013 onsite inspection, this letter is provided to clear up the confusion of asbestos material types and quantities provided on previous Asbestos NESHAP notifications.

The original notification did not provide accurate types and quantities of materials. The first revision was accurate with the exception of the 6510 square feet of RACM provided. The RACM was actually 510 square feet. The remaining 6000 square feet was for flooring plaster that contained less than 1% asbestos (as verified by the PLM point count method). I have provided a revised notification to this letter as an attachment that provides the correct quantities and types (as well as revising some of the "to be determined" information).

Also per your request, we have attached a copy of the asbestos survey that was conducted at the facility prior to renovation activities.

Please call if you need additional information.

Best regards,

R. Chris Crothers, Principal

Crothers Environmental Group, LLC

Private Consultant for the State of Vermont, Department of Buildings & General Services (BGS)

Encls: Revised Asbestos NESHAP Notification

cc: Brian Terhune, Project Engineer - BGS

Christopher Kinnick, Asbestos Control Engineer - Vermont Department of Health

CEG888200